BUILDING SAFETY CERTIFICATE

No. 392/10

Dated: 02-09-2023

Certified that the existing building Bill Clinton School at Ramrati Education Complex Delhi-Saharanpur, NH-709B, Rampur Maniharan, Saharanpur, U.P comprising of Nill basement(s) and Block-1 Consists-2 Floors, Block-2 Consists-2 Floors, Block-3 Consists-3 Floors, Block-4 Consists-2 Floors, Block-5 Consists-3 Floors, Block-6 Consists-2 Floors & Block-7 Consists-3 Floors owned/occupied by Bill Clinton School Ramrati Education Complex, Rampur Maniharan, Saharanpur, U.P. have complied with the Building bye laws in accordance with National Building code Rules state/UT and verified by the Assistant Engineer, Construction Division, Public Work Department, Saharanpur, UP on 02.09.2023 in the presence of Manager Mr. Saneesh. V.M at Ramrati Education Complex Delhi-Saharanpur, NH-709B, Rampur Maniharan, Saharanpur, U.P. During inspections of building and as per provided certificates of architect dated 02.09.2023 & NOC of fire department dated 02.09.2023 certificate and that the building/premises is fit for occupancy upto classes XII in accordance with rule and subject to compliance of the specific conditions as appended.

- Architect Certificate Attached
- 2. Fire NOC Attached

This Certificate Issued on 02/09/2023 at Bill Clinton School, Ramrati Education Complex. Rampur Maniharan, Saharanpur by

Designation: ASSISTANT ENGINEER, O/o THE EXECUTIVE ENGINEER. CONSTRUCTION DIVISION PWD. SAHARANPUR

BILL CLINTON SCHOOL Ramrati Education Complex, Rampur Maniharan, Saharanpur (U.P.)

BILL CLINTON SCHOOL Ramrati Education Complex, Rampur Maniharan, Saharanpur (U.P.)